



# LIGHTING CHECKLIST

- Blow out all your lights with compressed air.
- Wipe down all your lights, cleaning off all dust and haze.
- Wipe off lenses with cleaner, be sure to use the correct kind of cloth.
- Check the fans for any dust build up.
- Check your power adapter to make sure it is seated correctly and that it is not pulling too much current.
- Make sure each light has a safety cable and each clamp is tight.



# LIGHTING CONSOLE CHECKLIST

- Blow off the console and wipe down the screens getting finger prints, grease and dust off.
- Re-calibrate the screen.
- Check the software version and if it needs an update. Remember to backup the show file in two difference places before updating.



@lambdaav